



FOAMING BORE CLEANER

FOAMING BORE CLEANER

quickly and effortlessly dissolves and removes copper and powder residue. Its superior cleaning formula does the work for you, no brushing or other mechanical cleaning necessary.

- One-Step
- No Harsh Scrubbing
- Color Change Effectiveness Indicator

Directions:

Allow barrel to cool 5 minutes before use.

Shake can well.

1. Spray foam from chamber to muzzle
2. Wait 15-30 minutes for foam to clean.
3. Using a Hoppe's cleaning rod and patch, remove foam from barrel.

Note: Foam will turn blue indicating copper removal or black indicating powder removal.



SKU	DESCRIPTION	UPC	MSRP	MARKET RELEASE DATE
907	Foaming Bore Cleaner, 3oz Bottle	0-26285-00907-1	\$9.49	January 2016
908	Foaming Bore Cleaner, 12oz Bottle	0-26285-00908-8	\$12.95	January 2016